

00007 20 DEC 63

~~TOP SECRET~~

DIRECTOR

FROM

25X1

ACTION OPS 1-12

INFO :

TOR: 0703Z 20 DEC 63

25X1

IN 55417

PRIORITY

INFO

DATE

7787

25X1

103

25X1

A. G3256

25X1

B. GOOD

C. A DROP OFF IN QUALITY OCCURS TOWARD ALL OUTBOARD CORNERS OF THE FORMAT, WHICH IS NORMAL FOR CONFIGURATION S/N 118. PRESSURE ROLLER STATIC (CHATTER) IS PRESENT ALONG BOTH EDGES OF THE 9L FILM, AND ALONG THE INBOARD EDGE OF THE 9R FILM THROUGHOUT. THE VERTICAL INDICATOR DOT APPEARS OVER-EXPOSED AND BLOSSOMED. WEAK IMAGES OF THE ADJACENT POSITION INDICATOR LAMPS OCCUR WHEN THE CORRECT POSITION INDICATOR IS EXPOSED. METERING IS SLIGHTLY ERRATIC THROUGHOUT, BUT NO FORMAT OVERLAP OCCURS.

END OF MESSAGE

25X1

25 YEAR RE-REVIEW

~~TOP SECRET~~

GROUP 1
Excluded from automatic
downgrading and
declassification